

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-14594

INITIAL JJM	CUSTOMER ORDER NO.		ATTN TOM NAGLE			
DATE RECEIVED 06/30/93	DATE OPENED 07/07/93	DATE CODE RA 1-B0	SERIAL NUMBER A3200397	NEW SERIAL NUMBER	MODEL AND GRADE 700 7MMEXP BDL	
ACCESSORIES W/STUDS						

FROM:

SHIP TO:

Setup full
BALLARD, LYDDAN
HWY 106 EAST
P O BOX 829 - RIO HONDO MARINE
RIO HONDO TX 78583

BALLARD, LYDDAN
HWY 106 EAST
P O BOX 829 - RIO HONDO TX
RIO HONDO TX 78583

CUST NO: 080643 C.D.D.L.

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 059015	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	------------------------------	--------------------------------	------------	-----------	------------

- GUN CONDITION
- ☒ NEW
- ☐ LIGHTLY WORN
- ☐ WORN
- ☐ VERY WORN
- ☐ UNREPAIRABLE
- ☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	Fired when bolt was closed				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Upon receipt could not duplicate customer concern. However, examination revealed very heavy sticky gummy substance on action and trigger assembly. Bolt stop does not return, trigger has no movement.

PARTS	COMMENTS				
Called customer 7/3/93 and reviewed our findings. He stated rifle was purchased (new) 5 yrs ago. Only used for coast observation. Trigger pull 6 1/4 lbs. Gun left 012.	Unit returned. Upgraded to clean action and replace trigger assembly complete at N.C. No question of good work.				
REPAIRMAN HJB	PROOF	CLEAN ☒	TEST ☒	TARGET	PA
GALLERY TESTER	DATE	DATE	DATE	DATE	DA

OFFICE COPY

RD6925 RE

PS00965