

Dennis - T.P 4th

12/31

S.L. 012

Rust On Trig. Assy. Bedding Compound
On Trig. Assy. Barreled Action Appears
To Have Been Put In Another Stock
And Bedded $\frac{1}{2}$ Price Bedding
Sealant Missing On Fire Compound
Control

Martin