

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R91-23325

INITIAL CUSTOMER ORDER NO.

FPS RV51617

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
11/12/91	11/15/91	DI 9-88	C6303917		700 30-06 LH BDL
ACCESSORIES W/STUDS					

FROM:

L.L.BEAN
ACCOUNTING DEPT
CASCO ST
FREEPORT
USA

ME 04033

CUST NO: 033352 ILION

SHIP TO:

L.L.BEAN
RETAIL STORE
MORSE ST
FREEPORT
USAME
04033

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE						
TRIGGER GROUP					E1	F1
BOLT ASSY.					E2	F2
BARREL ASSY.					E3	F3
REC. ASSY.					E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

Trigger assembly has rusted from unknown source -
internal trigger parts not moving freely nor properly

PARTS

COMMENTS

1) repair bolt stop
2) replace trigger assembly at N/C
as gesture of good-will

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 8/9

PS01147