

File Number:	18874		Arms Service number:	63775	
Last Name:	BROMLEY		First Name:	JUSTIN	
Street:	23 FIELDVIEW ROAD		City:	BRADFORD	
State:	RI	Zip:	02808	Home Ph:	401-315-0109
Work Ph:		Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1008	
Concern:	FIRED ON BOLT CLOSING				
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	QUOTE REPAIR SPECIAL PRICE			Settlement Amount:	\$0.00
Date Opened Rem:	4/8/2003	Date Opened by P/S:	4/9/2003	Caliber:	270
Date of Incident:		Date Closed:	4/9/2003	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	C6243001	Date Code:	KI
RAMAC:	700	Date Mfgd:	5/6/1988	Litigation:	<input type="checkbox"/>
Custody:		PreLitigation:	<input type="checkbox"/>	Obsolete:	<input type="checkbox"/>
Time of Modification:	8:31:27 AM	<b>Comments:</b> Bolt release sticks due to sticky residue build up. Could not duplicate FOBC concern. Quote for new TA and cleaning action at 1/2 normal charges, quote for synthetic stock. Repair and shipping document 4/25/03.			
Date of Modification:	4/10/2003				