

Repair Order Number



Repair Order Number

RE00063775

Account # - R-

Description/Serial Number

C6243001

Model 700 Center Fire Caliber: 270

Repairman - Bruce Travis

Date Received - 4/17/2003

Estimate Date - 4/9/2003

Current Date - 4/23/2003

Customer

JUSTIN BROMLEY
23 FIELDSVIEW RD

BRADFORD, RI 02808 US

Return To

JUSTIN BROMLEY
23 FIELDSVIEW RD

BRADFORD, RI 02808 US

Phone (H) (401)-315-0109

Phone (W)

Fax

Email

Problems

Reported

M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION
M174 BOLT STOP STICKS
M992 FIRES ON CLOSING

Found

M123 FORWARD TO PRODUCT SERVICE F

Repair

Material # MaterialDesc

Quantity
Needed

Quantity
From Inv

Quantity
From Kit

Warranty
(Y/N)

Part

F106180 700 SYN STK ASSB MTN L/A
F26345 700 TRIG ASSB RH

Part Total:

1 1 0
1 1 0
2 2 0

Service

4000104 ARMS SERV SHIPPING & HANDLING
4000119 GR-TEST

Service Total:

0 0 0
1 1 0
1 1 0

ProblemNotes

trigger assm sticky from not being properly cleaned. quote for new trigger at 1/2 normal charge and
quote for black stock assm F.L.S. 04/09/03 repair as needed function test

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date