

THURSDAY 3-27-03

JUSTIN BROMLEY
23 FIELDVIEW RD.
BRADFORD, R.I. 02808
(401) 315-0109

SERIAL #
C6243001

DEPT. OF PRODUCT SERVICES:

THERE IS A PROBLEM WITH THE
ACTION ON MY MODEL 700. WHEN YOU
PERFORM THE ACTION, IT FIRES A ROUND.
ALSO THE BOLT SLIDES OUT OF THE SEAT
WITHOUT DEPRESSING THE RELEASE. THE
SERVICE REP SAID THAT THERE WILL
BE WAIVED FEES. ALSO I WANTED TO
CHECK ON AN ALL BLACK STOCK. PLEASE
CALL ME TO DISCUSS PROBLEM AND
STOCK.

Quote for new TA at

THANK YOU

1/2 normal charges -

Quote for all black stock.

Justin Bromley

TA sticky from not being
properly cleaned.

FCS
4/9/03

Attention
Of:

**PRODUCT
-SERVICE-**

Model:



RE00063775