Remington Arms Co. Arms Service Div. 14 Hoefler Ave Ilion,N.Y. 13357

Att: Jerry

)ear Sir:

As per our phone conversation on Dec. 22,1993, My Mod. 100 rifle has on one occasion delayed firing, two occasions if would not fire and the last time I took the rifle off afety and the rifle fired.

My mailing address is:

Patrick F. Byrne Box 281 Clum Hill Rd. Tannersville,N.Y. 12485

Sincerely,

Patrick Byrne