

I have had this rifle
for about 15 yrs and it
has given me no trouble
until last season. When the
temperature goes below 40°
it will not fire + the safety
malfunction also sometimes
when this happens and the
Bolt is operated the rifle
will fire

Sincerely
Howard J. Butters
202 York Rd
Sylvester Ga 31791

OFFICE COPY

RD925 REV. 1/84

PS01225