

RECEIVING AND ESTIMATING REPORT

COMMENTS

to Product Service

ORDER
R 93-27804

INITIAL FPS	CUSTOMER ORDER NO.	
DATE RECEIVED 12/09/93	DATE OPENED 12/16/93	DATE CODE EC 10-82
SERIAL NUMBER B6416126		NEW SERIAL NUMBER
MODEL AND GRADE 700 7MM MAG		BDL
ACCESSORIES W/STUDS		

L/REAR SIGHT

FROM:

SHIP TO:

Step Hill
**CORBY, FLOYD L.
BOX 347 RD 5
TUNKHANNOCK**

PA 18657

**CORBY, FLOYD L.
BOX 347 RD 5
TUNKHANNOCK**

PA 18657

CUST NO 0 00 1 .OLD L

ACCOUNT NUMBER	ACCOUNT NUMBER / VC 059015	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
----------------	--------------------------------------	--------------------------------	------------	-----------	-------------------

- GUN CONDITION
- ☐ NEW
 - ☒ LIGHTLY WORN
 - ☐ WORN
 - ☐ VERY WORN
 - ☐ UNREPAIRABLE
 - ☐ MARRED

- REPAIR CHARGE
- EXCISE
 - TAX
 - INSURANCE
 - UPS
 - PARCEL POST
 - TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1		E5	F5
METAL						
MAIN FAULT						

Refld mfg 1982
Upon receipt, unable to disassemble carbine chamber. Gunner would not let the action open trigger assembly on barrel with a heavy quantity of lubrication. But after volume will not retract.

COMMENTS

*Replace trigger assembly.
Clean action at 12 rounds
Adjustment cost, as gesture of good
will - per phone 1/18/94 Mr. Co*

REPAIRMAN <i>[Signature]</i>	PROOF	CLEAN	TEST	TARGET	PATTEE
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV. 1

PS01296