

CARROLL'S GUN SHOP, INC.

1612 N. Alabama Rd.
Wharton, Texas 77488
(979)532-3175
Fax (979-532-2810

Pat Cook
12/25

TO: Remington Arms Company, Inc.
14 Hoefler Avenue
Ilion, New York 13357
Attn: BL Safety

Repair Order No. #R-250 Date: Aug. 24, 2002

Enclosure:

Remington M-700 BDL, 22-250 cal. rifle, Ser. #6833832
w/1-piece Redfield base

Repair Order:

Please modify as per your safety update.

Our customer states that he has had an accidental discharge.

9/19/02 Action duty & trig adj
new action!

Serial Number:

6833832

Model: **700**



RE00052135

Estimate Request:

- ☐ Please
☐ Only if not covered by
☒ Only if charges are ov
☐ Not Necessary

We feel Item is:

- ☒ Covered by warranty
☐ Not covered by Warranty
☐ Unable to determine

2 days trig work
\$20.00

Signed:

Gloria Komucka

52135