

Dear Sirs

Enclosed is my Model 700 30-06 (Ser#6787947) bought for me, by my parents in the mid 70's. I am sending it in for the modification Program. In the mid 80's, while out hunting, the gun misfired when I took it off safety. This was the only time it ever happened.

If you have any questions or problems please call me
@ 406-723-6819 Days
406-723-7170 Nights

thanks

Mark Cerise

Please Return to: Mark Cerise

739 Utah Ave

Butte, Mt. 59701

DY= 9/74

Could not duplicate FSL concern.

Extremely dirty TA

Poor maintenance.

Install new TA, clean
action Quote #20 under
bolt lock modification program.

FLS 10/1/00

Serial
Number:

6787947

Model: 700



RE00052691