

File Number:	17930		Arms Service number:	51262	
Last Name:	CHAPEL SPORTS LTD		First Name:		
Street:	116-20 ATLANTIC AVENUE		City:	RICHMOND HILL	
State:	NY	Zip:	11419	Home Ph:	
Work Ph:	718-847-7661	Product Type:	F	F A T O	
Type Concern:	S	PI PD P S	Concern Code:	1028	
Concern:	FIRED WITH SAFE ON				
Cause Code:	4040	Cause:	OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To:	SUPRY	Classification:	UND	UNJ UNC UND J	
Settlement Detail:	BLM-P	Settlement Amount:	\$0.00		
Date Opened Rem:	8/27/2002	Date Opened by P/S:	8/28/2002	Caliber:	3006
Date of Incident:		Date Closed:	8/28/2002	Bullet Weight:	
Date to Analysis:		Date from Analysis:		Manufacturer:	
Model:	700	Serial:	B6340120	Date Code:	OB
RAMAC:	700	Litigation:	☐	PreLitigation:	☐
Custody:		Obsolete:	☐		
Time of Modification:	10:33:33 AM	Comments:	Could not duplicate concern. TA coated with sticky residue. Clean action and install new TA. Quote \$20.00 under bolt lock modification program. Repair and shipping documents 9/30/02.		
Date of Modification:	8/28/2002				