

Replace TIA, Clean Action
Quote \$20.00 under bolt lock
modification program.

Could not duplicate concern. TIA
Coated with sticky residue.

FLS 8/28/02

CHAPEL SPORTS LTD.

116-20 Atlantic Avenue
RICHMOND HILL, NEW YORK 11419
(718) 847-7661
FFL 6-11-041-01-2J-05238
N.Y.C. 05

SOLD BY:		DATE: 8/16/02	
NAME: Remington Arms		PHONE:	
ADDRESS: 14 Hoefler Ave			
CITY: Elton, NY 13357			
☐ CASH	☐ CHARGE	☐ MDSE. RETD.	PREVIOUS BALANCE
☐ C.O.D.	☐ PAID OUT	☐ PD. ON ACCT.	
Dear Sir,			
Enclosed is the			
Rem Model 700 30-06			
#B6340120. The gun fires			
on safe. Please replace			
as rec.			
Thank You			
J Beitzinger			
OB-7/81			
51262			

Serial Number: B6340120

Model: 700



RF000051262