

Serial Number:

6519654

Model: 700



RE00054063

Remington Arms

Attention Repairs

NOTE: Rifle Discharges When Removed
FROM Safety Position.

Model 700 BDL 25-06

S/N 6519654

Return Address

James E. Coulthard

4645 Blue Heron Dr.

Christiansburg, VA. 24073

54063

10/21/02

1007
4015

Date Recd

LW

2/72

Action & trigger assembly dirty & sticky substances
causing parts to work sluggish.

Replace trigger assembly & clean \$20.00