


285174

Model: 700



RE00048182

Page 1 of 1

Remington

Repair Form

(Fill out this form, and then include it with your firearm.)

Serial Number: 285174

Date of Purchase: 1974-75

Address (no PO Boxes):

2622 Park Road.

City: Eau Claire

Phone (Daytime): (616) 944-5716

State: Mich

Zip: 49111-9496

E-mail Address: brady@QTM.Net

Please describe your problem:

Safety Modification Program Model 700/40-X

Note: This Gun Has Discharged once
While operating the bolt. Factor
Loads

Additional Information: (Ammo type, brand, handload specifications, etc.)

.308 CAL - 180 Grain / 42 Grains of IMR
4320

NOTE: Prior to shipping your firearm, contact the Repair Center for services
provided and estimated repair time.

WARNING: DO NOT SEND LIVE OR SPENT SHELLS IN YOUR FIREARM OR IN THE SAME BOX WITH THE FIREARM.
THIS IS A VIOLATION OF FEDERAL LAW. IF YOU FEEL YOU MUST SEND SPENT SHELLS PLEASE SEND THEM IN A
SEPARATE PACKAGE AND INCLUDE NAME, ADDRESS (WITH ZIP CODE), TELEPHONE AND MODEL AND SERIAL
NUMBER OF YOUR FIREARM.

- :: Record the serial number of your firearm before sending it.
- :: Pack your firearm for safety and to prevent further damage in shipping and handling. Preferably,
ship in a firearm box. (Note: Original boxes may not be returned.)
- :: Remove all accessories from your firearm to prevent loss or damage.
- :: Ship your INSURED firearm by either UPS or Parcel Post. Remington is not responsible for
damage or loss during shipment, so you may elect to purchase insurance from your carrier.

48182

<http://www.remington.com/support/repairsvc/repairform.htm>

6/11/2002