

File Number:	20358	Arms Service number:	84535
Last Name:	CROWN ENTERPRISES	First Name:	
Street:	40 E IDAHO	City:	KALLISPELL
State:	MT	Zip:	59901
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F A T O
	PI PD P S	Concern Code:	1028
Concern:	FIRED WITH SAFE ON		
Cause Code:	4006	Cause:	ALTERED ADJUSTMENTS OR COMPONENTS
Assigned To:	SUPRY	Classification:	UND
Settlement Detail:	BLM PROGRAM		
Date Opened Rem:	9/2/2004	Date Opened by P/S:	9/2/2004
Date of Incident:		Date Closed:	9/3/2004
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	A6436078
RAMAC:	700	Litigation:	☐ PreLitigation: ☐ Obsolete: ☐
Custody:		Comments:	Could not duplicate concern. Adjustment screw settings altered, action dirty, TA coated with sticky residue. Clean action and install new TA - Quote \$20 under the bolt lock modification program.
Time of Modification:	9:42:26 AM		
Date of Modification:	9/3/2004		
Settlement Amount:	\$0.00		
Caliber:	8MM RM		
Bullet Weight:			
Manufacturer:			
Date Mfgd:	4/6/1977		