

SG R130337
CROWN ENTERPRISES
40 E. Idaho
KALISPELL, MT 59901

YOUR INVOICE NO. DATE
VIA SHIPPED DATE
EX 8-23-04
S. WEIGHT

IMPORTANT! ALWAYS SHOW INVOICES WITH
PACKAGES, CHECKS, RETURN INVOICES TO CREDIT
INVOICES AND CORRESPONDENCE

TO
ADDRESS Remington
CITY 14 Hoefter Ave
Illion
STATE NY
ZIP CODE 13357

CHARGE TO
ATTN: Repairs

APPROX. VALUE
☐ NOT ☐ IS
CHARGED TO YOU. DO NOT REBILL. BILL YOUR CHECK. ONLY EXTRA CHARGES.
CHARGED TO YOU. SEND US YOUR CHECK. DO NOT MAIL CREDITS.
VALUE SHOWN ONLY FOR INSURANCE PURPOSES

STORE CUSTOMER AUTH BY Ry-
Weiauder M 08 123 04

REPAIR MERCHANDISE LABEL

Please Hurry!
While You've Got It,
We Can't Sell It!

Our
Invoice
Tells You
What To Do

Please!
Don't Remove
This Tag
Return To Us
On Merchandise
Thank You

FROM

CROWN ENTERPRISES
40 E. IDAHO
KALISPELL, MT 59901

STORE DEPT.

CLASS	STYLE	DESCRIPTION	QUAN.	UNIT	COST	EXTENSION
		Model 700 - 8MM Rem Mag S/N - A6436078 Fires w/ Safety on				

REASON FOR RETURN AND/OR CHARGE:

1 Allowance	5 As Agreed	9 Over Charged	13 Subst'n
2 Authorized Return	6 Damaged	10 Over Shipped	14 Wrong Size
3 Cancelled Order	7 Exchange	11 Repair	15 Wrong Style
4 Color Wrong	8 Not As Ordered	12 Shortage	16 Not Ordered

AVOID ERRORS

Please Bill
Credits and Recharges
at
Terms Shown Here



SUB-TOTAL

☐ SERVICE CHARGES	
☐ INBOUND TRANSP.	
☐ RETURN TRANSP.	
TERMS	CLASS
DISCOUNT	TOTAL COST

INVOICE

R 130337

FORM 1656 RTV.

STANDARD RETAIL RETURN TO VENDOR AND CLAIM SYSTEM

Serial Number:

A6436078

Model: 700



RE00084535

could not duplicate
Trig. assm. dirty and has a sticky lubrication
valve causing parts to work sluggish. Replace
complete TPA under bolt lock safety program.
and clean action quote