

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
SERVICEORDER
R 94-24189INITIAL
JJMCUSTOMER ORDER NO.
72859DATE RECEIVED
08/19/94DATE OPENED
08/22/94DATE CODE
AS 3-69SERIAL NUMBER
6004020

NEW SERIAL NUMBER

MODEL AND GRADE
788 6MM

ACCESSORIES

W/STUDS

L/SIGHTS

L/CLIP

FROM:

CARTERS COUNTRY
6310 TRESCHWIG RD
SPRING

TX 77373

SHIP TO:

CARTERS COUNTRY
6310 TRESCHWIG RD
SPRINGTX
77373

CUST NO:006469 WILM L

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

20.5

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

B2

BOLT ASSY.

B3

BARREL ASSY.

B4

REC. ASSY.

B5

WOOD

C1

D3

E5

F5

METAL

C2

MAIN FAULT

Trigger housing lock screw loose. Causing trigger assembly to move
when safety assembly is released. Did not show fault in this condition.
Life Aug. 1969 We could not duplicate this premature firing.

PARTS

COMMENTS

Screw is needed at same price

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

to A/S

8/30/94

RD6925 REV. 1/94

PS01370