

Repair Order Number



Repair Order Number RE00074538	Description/Serial Number A6281132	Repairman - Herb Brown Date Received - 1/15/2004
Account # - R-	Model 700 Center Fire Caliber: 3006 BDL	Estimate Date - 1/6/2004 Current Date - 1/28/2004
Customer DELBERT COVINGTON 103 MARSHALL RD GLEN MILLS, PA 19342 US		Return To DELBERT COVINGTON 103 MARSHALL RD GLEN MILLS, PA 19342 US
Phone (H) (610)-459-0693 Phone (W)	Fax Email	

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE FOR
M992	FIRE WHEN TAKEN OFF SAFE	M239	REPLACE TRIGGER ASSEMBLY

		Repair			
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	10	10	0	Y
Service Total:		31	31	0	

ProblemNotes	Could not duplicate customers concern. Sticky residue- trigger return sluggish. Quote for new trigger and cleaning action under bolt lock modification program.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date