

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER

R 94-31399

INITIAL
FPS

CUSTOMER ORDER NO.

W/BOTTOM HALF OF SCOPE MOUNTS

DATE RECEIVED

DATE OPENED

DATE CODE

SERIAL NUMBER

NEW SERIAL NUMBER

MODEL AND GRADE

11/01/94

11/03/94

KN 5-93

S6234014

700

338 WIN

MAG/SS/BDL

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

SHIP TO:

CREAMER, DAVID
489 COSSADUCK HILL
N STONINGTON

CT 06359

CREAMER, DAVID
489 COSSADUCK HILL
N STONINGTON

CT
06359

CUST NO:044903 C.O.DL

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

PROM. DATE

ESTIMATED

VIA

063103

WRITE ☐

UPS

GUN CONDITION

- ☐ NEW
☐ LIGHTLY WORN
☒ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

*Poorly maintained
11/11/94*

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

Fire when the safety is released

B3

B4

B5

C1

C2

D1

D2

D3

E2

E3

E4

E5

F2

F3

F4

F5

MAIN FAULT

Mfga 3/93 Firing pin drops when bolt is released. Trigger rusted and does not return. Gun has been poorly maintained. Install new trigger assy at a special price strictly as a gesture of good will. Clean action best possible. See owners manual for proper care and maintenance.

PARTS

COMMENTS

Unable to take trigger pull as rec'd

Trigger rusted in housing

Firing pin and spring rusted

Bolt face rusted

Extreme fouling in bore

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS01481