

Serial
Number:

A6728142

Model: 700



RE00022424

2/9/01

Refle prematurely discharged when the
safety is released.

Upon receipt the bolt stop release, rear safety cam
& trigger working sluggish from being covered
with dirt & a brown sticky substance.

Refle poorly maintained.

Replace trigger cam & clean action at
1/2 MSP JP ahead