

John Dill  
301 Dominic Drive  
Scott Depot, WV 25560  
(304) 757-9530  
(304) 586-0616 Work  
(304) 586-0620 Fax  
[Multicoatjohn@aol.com](mailto:Multicoatjohn@aol.com)

June 17, 2002

Remington Arms Company, Inc.,  
Ilion Firearms Plant  
Attention: BL Safety Program  
14 Hoefler Avenue  
Ilion, NY 13357

*Date Code*  
*LO 2/17*

RE: Bolt-Lock

Gentlemen:

I am enclosing a Remington Model 700 30.06, serial number A 6412952 which is eligible for the replacement trigger assembly.

Please apply payment (up to \$75) on the following credit card:

Private Issue:  
6011 3006 6065 4235  
Exp: 09/02

*←*

*1007*  
*4015*

*48378*

If there are any questions, please reach me on one of the phone numbers found at the top of this letter. The person I spoke with in customer service said it will be approximately 2 - 3 weeks before I will receive the gun back.

Thanks in advance.

John Dill

*6/25/02*

*Refund for whom safety is moved to for -*  
*Action & trigger assembly Poorly maintained*  
*Refund trigger assembly 20.00*  
*Credit Card*