

RE000048784



Model: 700


Serial
Number:

C6283450

TO WHOM IT MAY CONCERN (2)
REMINGTON,

THIS RIFLE MAY HAVE COME
PACKED WITH TRIGGER MECH.
PACKED WITH SHIPPING
GREASE, I DO NOT KNOW.

BUT TRIGGER PULL CONTIN-
UOUSLY GOT WORSE. VERY
HARD, COULD NOT KEEP ON
TARGET - COLD WEATHER
VERY DETRIMENTAL. HAD
IT CLEANED, AM NOT SURE
IF IT WAS ADJUSTED IN
ANY WAY. THIS FALL I
DID NOT GET MY MOOSE AND
ALMOST NOT A BUCK - FIRST
SHOT FIRED, BUT VERY HARD
TRIGGER PULL, AFTER THAT
RIFLE WOULD NOT FIRE AT ALL.
→



FOUND OUT, I COULD LOAD
SINGLY - LIFT BOLT-AND
DOWN- SAFETY- WOULD FIRE.
ONCE WHILE CLOSING BOLT
BEFORE RIFLE WENT OFF!
NO FINGER ON TRIGGER!

DO NOT TRUST SAFETY, NOR
TRIGGER & BOLT ASSEM.
PLEASE HELP ME REGAIN MY
FAITH IN THIS RIFLE/ I LOVE
350 WHELEBY CAL.

BEKM NOTE CARDS*
10 Champlain St. • Berlin, NH 03570

C6283450

Model: 700



RE00048784

Serial Number:

Could not duplicate -
Some sticky residue & dirty
Action.

Clean, install new TA n/c as
gesture of goodwill.


Charge 230145

FCS 7/10/02

Serial
Number:

C6283450

Model: **700**



RE00048784