Arms Service number: 50752 Last Name: DEAN
Street: 4050 FOREST HILLS LANE City: SILSBEE State: TX Zip: 77656 Home Ph:
State: TX
Work Ph: Product Type: F F A T O Type Concern: S PI PD P S Concern Code: 1007 Concern: FIRED ON SAFE RELEASE Cause Code: 4006 Cause: ALTERED ADJUSTMENTS OR COMPONENTS Assigned To: SUPRY Classification: UND UNJ UND UNJ UND UND J Settlement Detail: BLM PROGRAM Settlement Amount: \$0.00 Date Opened Rem: 8/14/2002 Date Opened by P/S: 8/15/2002 Caliber: 3006
Type Concern: S PI PD P S Concern Code: 1007 Concern: FIRED ON SAFE RELEASE Cause Code: 4006 Cause: ALTERED ADJUSTMENTS OR COMPONENTS Assigned To: SUPRY Classification: UND UNJ UNC UND J Settlement Detail: BLM PROGRAM Settlement Amount: \$0.00 Date Opened Rem: 8/14/2002 Date Opened by P/S: 8/15/2002 Caliber: 3006
Cause Code: 4006 Cause: ALTERED ADJUSTMENTS OR COMPONENTS Assigned To: SUPRY Classification: UND UNJ UNC UND J Settlement Detail: BLM PROGRAM Settlement Amount: \$0.00 Date Opened Rem: 8/14/2002 Date Opened by P/S: 8/15/2002 Caliber: 3006
Assigned To: SUPRY Classification: UND UNJ UNC UND J Settlement Detail: BLM PROGRAM Settlement Amount: \$0.00 Date Opened Rem: 8/14/2002 Date Opened by P/S: 8/15/2002 Caliber: 3006
Settlement Detail: BLM PROGRAM Settlement Amount: \$0.00 Date Opened Rem: 8/14/2002 Date Opened by P/S: 8/15/2002 Caliber: 3006
Date Opened Rem: 8/14/2002 Date Opened by P/S: 8/15/2002 Caliber: 3006
Caliber, poor
Date of Incident: Date Closed: 8/20/2002 Bullet Weight:
Date to Analysis: Manufacturer:
Model: 700 Serial: A6672590 Date Code: Date Mfgd: 7/25/1979
RAMAC: 700 Litigation: PreLitigation: Obsolete:
Custody: Comments: Could not duplicate concern. TA settings altered, Clean and install new TA under bolt lock modification program. Quote customer \$20.00
Time of Modification: 1:24:35 PM
Date of Modification: 8/20/2002