

Remington

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00057613	Description/Serial Number S6417390	Repairman - Robert Frink
Account # - R-	Model 700 Center Fire Caliber: 300 WIN	Date Received - 12/16/2002
	MAG	Estimate Date -
		Current Date - 12/30/2002
Customer NATHAN DEPPE 3149 YEATES RD NEW HAVEN, MO 63068 US		Return To NATHAN DEPPE 3149 YEATES RD NEW HAVEN, MO 63068 US
Phone (H) (636)-239-7178		Fax
Phone (W) (573)-237-7178		Email

Problem	
Reported	Round
M123 FORWARD TO PRODUCT SERVICE FOR INSPECTION	123 FORWARD TO PRODUCT SERVICE F
M992 BOLT STOP/RELEASE BINDS	

Repair					
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F97490	700 SS TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		1	1	0	

ProblemNotes Could not duplicate. Install new trigger assen check over completely at n/c. FLS 12/18/02.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

PS01718