

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number

RE00086482

Description/Serial Number

A6219548

Repairman - Herb Brown

Date Received - 10/19/2004

Account # - R-

Model 700 Center Fire Caliber: 300 BDL
CLASSIC

Estimate Date -

Current Date - 10/22/2004

Customer

WILLIAM DONAN
6220 ISLAND FORD RD

Return To

WILLIAM DONAN
6220 ISLAND FORD RD

HANSON. KY 42413 US

HANSON. KY 42413 US

Phone (H) (270)-322-8537

Fax

Phone (W)

Email

Problems

Reported

M123 FORWARD TO PRODUCT SERVICE
FOR INSPECTION
M240 BOLT LOCK SAFETY MODIFICATION
M992 MISFIRED WHILE CHAMBERING

Found

M123 FORWARD TO PRODUCT SERVICE F
M238 CLEAN & INSPECT (SAFETY PROGR.
M239 REPLACE TRIGGER ASSEMBLY

Repair

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
4000294	GR-CHECK TPA	1	1	0	Y
Service Total:		3	3	0	

ProblemNotes

Could not duplicat customers concern. Supply new trigger assm. at nc.

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

PS01771