Remington	
Factory Repair Instructions (NOTE: Please print and complete this form, and then include it with your firearm.)	
Model Number: 700 Mountain Rifle DM	
Are you the original owner?: YES NO	
Name: Jeffrey L. Davis	Date of Purchase: 8-11-02
Address (no PO Boxes): 1427 Country Ridge Road	
city: Bassett	State: VA Zip: 24055
Phone (Daytime): 276 - 956 - 7768	
E-mail Address: jjKcdav 15 & Kimbanet.com I would like to receive future e-mail updates from Remington.	
Please describe your problem: Rifle has fired 3 time	
at different times by just clicking	
Safety to fire posit	ion. Twice, while
lining up scope in October 2003. Bok trigger	
assy: out and sprayed with WD40. Didnot see	
any foreign meterial or trash. Then again in	
Nov. 2004. I have lost all confidence in	
safety of this rifle.	
Ammunition Information:	
Manufacturer: Remington	Type: Premier Ballistic Tip
Other (i.e. bullet weight/type, shot size, powder):	120 Gr. Nosler
Handload Information:	
Powder Used:	Douglay Walakt
Case/Hull Used:	Powder Weight:
	Primer Used:
Bullet Type/Shot Size:	Reloader Used:
Firearms Care (Cleaning and Lubrication):	
Brand of cleaning solution used: Outers Nitro Solvent	
How often do you clean the bore? (Months or Number of rounds) After nunting season How often do you clean the action? (Months or Number of rounds) During Season-after Season	
How often do you clean the trigger assembly? (Months or Number of rounds) Was deaned	
after 1st mistire about 15 rounds.	
Brand of lubricant used: Rem. Oil	
How often do you lubricate the bore? (Months or Number of rounds) Each cleaning	
How often do you lubricate the action? (Months or Number of rounds) Fach Cleaning	
How often do you lubricate the trigger assembly? (Months or Number of rounds) After cleaning	
Have you reviewed the cleaning and maintenance recommendations on our web site or in our owners manual? YES NO	
'	· (

http://www.remington.com/support/repairsvc/factrep.htm

11/21/2004