

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00081328	Description/Serial Number E6746958	Repairman - Robert Frink Date Received - 5/27/2004
Account # - R-	Model 700 Center Fire Caliber: 3006 ADL SYNTHETIC	Estimate Date - Current Date - 6/3/2004
Customer DEER RIDGE BAIT 2427 U S HIGHWAY 25 E MIDDLESBORO. KY 40965 US		Return To DEER RIDGE BAIT 2427 U S HIGHWAY 25 E MIDDLESBORO. KY 40965 US
Phone (H) (606)-242-2248 Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRES WHEN TAKEN OFF SAFE		

Repair					
<u>Material #</u>	<u>MaterialDesc</u>	<u>Quantity Needed</u>	<u>Quantity From Inv</u>	<u>Quantity From Kit</u>	<u>Warranty (Y/N)</u>
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000118	GR-CLEAN	1	1	0	Y
Service Total:		2	2	0	

ProblemNotes	Sticky residue. Could not duplicate. Install a new trigger assembly and clean action at no charge under warranty. FLS 5/27/2004.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date