

DON'T SAY IT—WRITE IT

To Arms Service Location 52-2
From J. STEKL Location PRODUCT SERVICE Phone No. _____
Subject #70-06210, m/700BPL 270win. CALIBER; S.N. 6479664 Date 3/12/50

Tommy Dziak

The customer has accepted our offer to replace the trigger assembly on the subject rifle at no-charge, as a gesture of good-will.

His check for 10.00 to cover handling is attached.

Please install the above A.S.A.P., and return the rifle to the sender transportation C.O.D.

Thank you,
Jas.

RD 779

STOP, LOOK, AND LIVE

CLARE CHECK

5639

MR. OR MRS. THOMAS R. DZIUK, JR. 5-73

131 HATCHER 333-8212
SAN ANTONIO, TX 78223

3-5 1990

PAY TO THE ORDER OF Pennington Arms Co. Inc. \$ 10.00/4

Ten and no/100 DOLLARS

 NBC Bank San Antonio n.a.
Brooks Field
P.O. BOX 23250 SAN ANTONIO, TEXAS 78286 512/533-3131

FOR gas repairs

Thomas R Dziuk

⑆1114000116⑆11 00386901⑆ 5639