

From:

Fred Supry

Remington Arms
Ilion, NY 13357

315-895-3606

Date 10/25

6659265 OX = 7/23

→ Sticky residue

Bolt Release sluggish


Could not duplicate concern.

Customer used WD-40 before
storing gun - recommended that
he not use WD-40 because of sticky
residue left on internal parts.

Serial
Number:

6659265

Model: 700



RE00034414