

I was advised, by the factory to send this rifle, a Remington model 700 BDL - Serial # A 6688306, to the factory to be serviced.

The problem is: When the safety was taken off, the rifle fired, without anyone pulling the trigger. I believe it might be a factory defect.
(Recall)

Reginald Horn, Sr.

37 Taylor Hill

Proctor, VT. 05765

Sent back to factory - Nov. 26, 2001

Serial
Number:

A6688306

Model: **700**



RE00037146