

RECEIVING AND ESTIMATING REPORT

COMMENTS

Product
ServiceORDER
R 97-19204

CUSTOMER ORDER NO.

JJM

DATE RECEIVED

11/06/97

DATE OPENED

11/07/97

DATE CODE

RP 11-67

SERIAL NUMBER

317965

NEW SERIAL NUMBER

MODEL AND GRADE

700 22-250

BDL/VAR

ACCESSORIES

W/STUDS

SCOPE BASE

FROM:

DICKS COUNTRY STORE
7429 RT 11 BOX 103
CHURUBUSCO

NY 12923

SHIP TO:

DICKS COUNTRY STORE
7429 RT 11 BOX 103
CHURUBUSCONY
12923

CUST NO:007792 WILM

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE

FROM DATE

ESTIMATED

VIA

11-11-97

UPS

GUN CONDITION

- ☐ NEW
☒ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

28.00

8.00

36.00

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

MAIN FAULT

Owner says the rifle was broken when the
bolt was stuck.

Rifle mfg 1967 upon receipt the rear sight cover & bolt
stop were stuck up, the rear sight cover & bolt
were covered with a heavy sticky substance. The trigger
adjustment & stop screws have been re-set. Trigger 2 1/2
lb. & compact hammer properly maintained.

26345

Replace the complete trigger assembly
& clean the action to the
normal repair cost.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTERN

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

108925 REV 11/97

PS02055