

409308

Model: 722



RE00061917

COINS

tion!

246 Bradford Rd.
Plattsburgh, NY 12901
Toll Free # 1-800-273-8739
Phone: (518) 563-9373

Model: 722

Ser.#: 409 308

Name: John C. Downey

Date of purchase: 1989-60

2/17/03

Address: 26 McCutcheon Lane

Saranac, N.Y. 12981

30 January 2003

Phone: 518-293-8870

Email: downeyjc@westelcom.com

Describe problem:

The rifle discharged as the bolt was closed. The trigger was not touched during the process.

Please replace the trigger mechanism. Enclosed is a check for \$20.00 as per instructions on your web site.

Rem 722

409308

lev with

Check # 2900

61917

Sincerely,

John C. Downey

Thank you

Mary Jane

2/24/03 Action & trigger assembly checked
w/ proper safety substitution. No issues noted
Replaced trigger assembly \$20.00 Rmt