

24 July 95

RAY DOWNS
RT-1, Box 70-F1
ITALY, IX 76651
PH 214-312-2585

Dear Remington Arms, Service Center

Enclosed please find my
mod 700 30-06 BDL, SN# 627889.

The problem is that on occasion
(once so far) it fails when the
saftey was taken off to open the
bolt to unload.

Please fix this so I can
unload with the saftey left
on.

Thanks Ray

Please call 214-312-2585 if
you have questions

P.S. Other than that it's a great
shooter.