

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 93-09360

INITIAL JIM	CUSTOMER ORDER NO. 1754				
DATE RECEIVED 04/02/93	DATE OPENED 04/07/93	DATE CODE KO 5-77	SERIAL NUMBER A6457103	NEW SERIAL NUMBER	MODEL AND GRADE 700 243 BDL
ACCESSORIES W/STUDS					

FROM:

SHIP TO:

EAGLES ARMS SPORTS SHOP
BOX 35 RTE 222
BREINIGSVILLE

PA 18031

EAGLES ARMS SPORTS SHOP
BOX 35 RTE 222
BREINIGSVILLE

PA

18031

CUST NO: 008022 WILM L

ACCOUNT NUMBER	ACCOUNT NUMBER N/C	WRITE ☐	PROM. DATE	ESTIMATED	VIA UPS
GUN CONDITION					REPAIR CHARGE 25.00
☐ NEW					EXCISE
☐ LIGHTLY WORN					TAX
☐ WORN					INSURANCE
☐ VERY WORN					UPS
☐ UNREPAIRABLE					PARCEL POST
☐ MARRED					TOTAL

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	
BARREL ASSY.		B4		D1	E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			C1	D3	E5	F5
METAL			C2			

MAIN FAULT

After 1977 - Unable to duplicate customer concern.
Elimination of several things, mostly in relation on action and
trigger assembly. Bolt stop where trigger movement.
Trigger Pull - 5 lb
Gun left 008

RTS

COMMENTS

Repaired trigger assembly complete
at 1/2 normal replacement cost, and
clean action, all features of good use
GP advised per phone call on 5/1

REPAIRMAN	PROOF	CLEAN ☒	TEST ☒	TARGET	PATTE
GALLERY TESTER	DATE	DATE	DATE	DATE	DATE

OFFICE COPY

RD6925 REV.

PS02132