

Repair Order Number



Repair Order Number RE00071750	Description/Serial Number A6839523	Repairman - Dave Dunckel
Account # - R-	Model 700 Center Fire Caliber: 270 WIN	Date Received - 10/31/2003
	BDL	Estimate Date - 10/28/2003
		Current Date - 11/4/2003
Customer CHRIS ENEVOLDSEN 29833 E 155TH ST S COWETA. OK 74429 US		Return To CHRIS ENEVOLDSEN 29833 E 155TH ST S COWETA. OK 74429 US
Phone (H) (918)-251-1141 XW		Fax
Phone (W) (918)-706-3339 XC		Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M993	DELAY FIRED		

Repair					
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F17017	700 EJECTOR .	1	1	0	Y
F17019	700 EJECTOR SPRING	1	1	0	Y
F26345	700 TRIG ASSB RH	1	1	0	Y
F28712	700 BOLT ASSB L/A CS F1	1	1	0	Y
F93712	700 EXTRACTOR REG (7400;710)	1	1	0	Y
F94555	700 EJECTOR PIN (SPIROL)	1	1	0	Y
Part Total:		6	6	0	
Service					
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000117	GR-PROOF	1	1	0	Y
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		4	4	0	

Condition	Date of Mfg: Dec 1979				
Problem/Notes	Note: Return Scope Mts to Customer Purchased 2nd Hand-Bolt Shroud Upset-Trig Assy Dirty-Parts working sluggish-Poor Maintenance-Replace Bolt Assy & Trig Assy at N/C-per G. Sevall (Loanoke)-Polish Chamber-Send to Gallery for Proof & Test				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date

Serial
Number:

A6839523

Model: 700



RE00071750