

File Number: 19613		Arms Service number: 73997	
Last Name: ED'S GUN SHOP		First Name:	
Street: 5560 US HWY 1		City: VASS	
State: NC	Zip: 28394	Home Ph:	
Work Ph: 910-692-4867	Product Type: F F A T O		
Type Concern: S	PI PD P S	Concern Code: 1008	
Concern: FIRED ON BOLT CLOSING			
Cause Code: 4040	Cause: OTHER - UNSPECIFIED OR UNDETERMINED		
Assigned To: SUPRY	Classification: UND	UNJ UNC UND	
Settlement Detail: NEW TA N/C	Settlement Amount: \$65.00		
Date Opened Rem: 12/15/2003	Date Opened by P/S: 12/16/2003	Caliber: 270	
Date of Incident:	Date Closed: 12/16/2003	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer:	
Model: 700	Serial: D6596308	Date Code:	Date Mfgd: 4/29/2001
RAMAC: 700	Litigation: <input type="checkbox"/>	PreLitigation: <input type="checkbox"/>	Obsolete: <input type="checkbox"/>
Custody:	Comments: Could not duplicate concern. Bolt release movement sluggish due to sticky residue. Install new TA and clean action at n/c as gesture of goodwill. Repair and shipping documents 12/30/03.		
Time of Modification: 7:54:19 AM			
Date of Modification: 12/16/2003			