

Repair Order Number



Repair Order Number

RE00073997

Description/Serial Number

D6596308

Repairman - Dale Lewis

Date Received - 12/15/2003

Account # - R-

Model 700 Center Fire Caliber: 270
MOUNTAIN DM

Estimate Date -

Current Date - 12/18/2003

Customer

EDS GUN SHOP
5560 US HWY 1

Return To

EDS GUN SHOP
5560 US HWY 1

VASS. NC 28394 US

VASS. NC 28394 US

Phone (H) (910)-692-7936

Fax (910)-692-4867

Phone (W)

Email anicely@mindspring.com

Problems

Reported	Found
M123 FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123 FORWARD TO PRODUCT SERVICE FOR
M992 FIRES ON CLOSING	

Repair

Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000294	GR-CHECK TPA	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		2	2	0	

ProblemNotes could not duplicate bolt relase sluggish due to sticky residue.install new ta clean action n/c per product service

Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date