



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00070799	Description/Serial Number A6358709	Repairman - Robert Frink Date Received - 10/3/2003
Account # - R-	Model 700 Center Fire Caliber: 270 ADL	Estimate Date - Current Date - 10/9/2003
Customer EDS GUN SHOP 1411 CR 107 NEW ALBANY. MS 38652 US		Return To EDS GUN SHOP 1411 CR 107 NEW ALBANY. MS 38652 US
Phone (H) (662)-534-0551 Phone (W)		Fax Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	CHECK SAFETY / MISFIRING		

Repair					
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000116	GR-LABOR	20	20	0	N
4000118	GR-CLEAN	1	1	0	Y
4000119	GR-TEST	1	1	0	Y
Service Total:		22	22	0	

ProblemNotes	Action and trigger assembly dirty. All trigger adjustment screws altered. Clean action and replace complete trigger assembly. D.S.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date