

RECEIVING AND ESTIMATING REPORT

COMMENTS

P. Hoaden
ServiceORDER
R 99-02361

INITIAL FJB	CUSTOMER ORDER NO.					
DATE RECEIVED 01/18/99	DATE OPENED 01/25/99	DATE CODE LS 2-98	SERIAL NUMBER E6437394	NEW SERIAL NUMBER	MODEL AND GRADE 700 30-06	BDL
ACCESSORIES W/STUDS						

ENHANCED

FROM

SHIP TO:

ELLETT BROTHERS
267 COLUMBIA AVE
CHAPIN

SC 29036

ELLETT BROTHERS
267 COLUMBIA AVE
CHAPINSC
29036

CUST NO: 006063 WILM

ACCOUNT NUMBER	ACCOUNT NUMBER N/C 230145	WRITE ☐	PROM DATE	ESTIMATED 1-27-99	VIA UPS
GUN CONDITION			REPAIR CHARGE		
☐ NEW			EXCISE		
☐ LIGHTLY WORN			TAX		
☐ WORN			INSURANCE		
☐ VERY WORN			UPS		
☐ UNREPAIRABLE			PARCEL POST		
☐ MARRED			TOTAL		

CUSTOMER CONCERN	AMMO	FUNCTION	FINISH	ACCURACY	FIT	INSPECT
CYCLE	A1	B1				
TRIGGER GROUP		B2			E1	F1
BOLT ASSY.		B3			E2	F2
BARREL ASSY.		B4			E3	F3
REC. ASSY.		B5		D2	E4	F4
WOOD			B1	B3	E5	F5
METAL						
IN FAULT						

Unable to duplicate customer. Completely disassembled trigger assembly. no fault found

PTS	COMMENTS
#26345	Replace the complete trigger assembly at no charge
1000	
4000	

REPAIRMAN MBS	PROOF	CLEAN ☒	TEST ☒	TARGET
GALLERY TESTER	DATE	DATE	DATE	DATE

OFFICE COPY

RD6921

PS02190