



TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00068575	Description/Serial Number 69672	Repairman - Herb Brown
Account # - R-	Model 600 Center Fire Caliber: 6.5 REM	Date Received - 8/11/2003
	MAG	Estimate Date -
		Current Date - 8/13/2003
Customer LEONARD EVERMAL 146 HILLSBORO ROAD CAMDEN, NY 13316 US		Return To LEONARD EVERMAL 146 HILLSBORO ROAD CAMDEN, NY 13316 US
Phone (H) (315)-245-3143		Fax
Phone (W)		Email

Problems			
Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRES WHEN CLOSING BOLT	M176	RETURNED FOR RECALL/UPDATE

Material #		MaterialDesc		Repair			Warranty
				Quantity Needed	Quantity From Inv	Quantity From Kit	(Y/N)
Part							
F91469		600 TRIGGER ASSB		1	1	0	Y
Part Total:				1	1	0	
Service							
4000104		ARMS SERV SHIPPING & HANDLING		0	0	0	Y
4000119		GR-TEST		1	1	0	Y
Service Total:				1	1	0	

ProblemNotes	Update with new trigger assm. Find no fault with receiver screw . Tap out receiver plug screws.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date