

File Number:	11113	Arms Service number:	9828170
Last Name:	ELLETT BROTHERS	First Name:	
Street:	287 COLUMBIA AVE	City:	CHAPIN
State:	SC	Zip:	29036
Work Ph:		Home Ph:	
Type Concern:	S	Product Type:	F A T O
PI	PD	P	S
Concern Code:	1007	Concern Code:	1007
Concern:	FIRED ON SAFE RELEASE		
Gauge Code:	4040	Cause:	OTHER - RUSTED FROM UNKNOWN SOURCE
Assigned To:	SUPRY	Classification:	UND
Settlement Detail:	REPAIR N/C	UNJ	UNC
Date Opened Rem:	12/29/1996	Date Opened by P/S	01/12/1999
Date of Incident:		Date Closed:	01/12/1999
Date to Analysis:		Date from Analysis:	
Model:	700	Serial:	EG485939
RAMAC:	700	Date Code:	DS
Custody:		Manufacturer:	REM
		Date Mfgd:	09/01/1998
		Obsolete:	☐
		PreLitigation:	☐
		Comments:	Could not duplicate customer concern. The trigger was rusted from unknown source. Replace FC under warranty.
Time of Modification:	12:37:02 PM	Date of Modification:	01/12/1999