

Serial
Number:

377702

Model: 700



RE00024525

3/19/01

Date Code EP
10/68

4-5 occasions has failed when safety was
moved to the position

This 1968 mfg has not been cleaned in yrs.
the action & trigger housing are covered with
dirt, dust & grime. Poorly maintained.
Stroke arm has not been removed from action
in yrs.

1007
4015

Replace trigger arm & clean action 1/2 MSP
90 check