

RECEIVING AND ESTIMATING REPORT

COMMENTS

R 92-00000

INITIAL
JJM

CUSTOMER ORDER NO.

DATE RECEIVED
12/20/91DATE OPENED
01/02/92DATE CODE
ER 10-68SERIAL NUMBER
376577

NEW SERIAL NUMBER

MODEL AND GRADE
700 30-06

ADL -

ACCESSORIES

W/STUDS

SCOPE BASE

L/SIGHTS

FROM:

FRED'S GUN EMPORIUM
3003 SLIDE RD
LUBBOCK
USA

TX 79407

SHIP TO:

FRED'S GUN EMPORIUM
3003 SLIDE RD
LUBBOCK
USA

TX

79407

CUST NO: 006566 ILION

ACCOUNT NUMBER

ACCOUNT NUMBER N/C

WRITE ☐

CLEAN/TEST

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

☐ NEW☐ LIGHTLY WORN☐ WORN☐ VERY WORN☐ UNREPAIRABLE

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

TRIGGER GROUP

BOLT ASSY.

BARREL ASSY.

REC. ASSY.

WOOD

METAL

Trigger goes off when bolt action is closed

B2

B3

B4

B5

C1

C2

E1

E2

E3

E4

E5

F1

F2

F3

F4

F5

MAIN FAULT:

Received w/ stick-crack at mag. box - mfg. 1968
Cannot duplicate complaint - however, inspecting trigger assembly is
contaminated with a gummy, sticky residue - internal trigger parts
are not moving freely, nor properly. Sear-safety cam is sticking &
side plate of trigger housing - rifle has not been properly maintained.
trigger pull 5 1/2 pounds; sear-lift .006"

PARTS

COMMENTS

Based on mag. & trigger
replacement trigger assembly
at normal cost, as a gesture of
good-will.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATI

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

PS02320