

RECEIVING AND ESTIMATING REPORT

COMMENTS

ORDER
R 94-36811

INITIAL CUSTOMER ORDER NO.

EFS

DATE RECEIVED	DATE OPENED	DATE CODE	SERIAL NUMBER	NEW SERIAL NUMBER	MODEL AND GRADE
12/13/94	12/20/94	AD 3-94	56247729		700 300 WEY MAG/SS/BD
ACCESSORIES W/STUDS					

FROM:

SHIP TO:

FRONTIERSMAN
F ANTONOWICZ, GUNSMITH
6925 WAYZATA BLVD
MINNEAPOLIS MN 55426

FRONTIERSMAN
F ANTONOWICZ, GUNSMITH
6925 WAYZATA BLVD
MINNEAPOLIS MN 55426

CUST NO: 002662 WIEM

ACCOUNT NUMBER

ACCOUNT NUMBER NO

054001

WRITE ☐

PROM. DATE

ESTIMATED

VIA

UPS

GUN CONDITION

- ☒ NEW
☐ LIGHTLY WORN
☐ WORN
☐ VERY WORN
☐ UNREPAIRABLE
☐ MARRED

Shell clearance cut at rear bridge
of the Receiver is shallow
Sent 1/12/95

REPAIR CHARGE

EXCISE

TAX

INSURANCE

UPS

PARCEL POST

TOTAL

CUSTOMER CONCERN

AMMO

FUNCTION

FINISH

ACCURACY

FIT

INSPECT

CYCLE

A1

B1

TRIGGER GROUP

BOLT ASSY.

B3

BARREL ASSY.

B5

REC. ASSY.

B5

WOOD

C1

D3

METAL

C2

D3

MAIN FAULT

Mfg. 3/44 Trigger pounds pull screw has been altered
outside of the factory, reset to factory specs.

PARTS

COMMENTS

Trigger pull measured 2 #s on
Rec'd. sent. lift was .012

Seal engagement .017

We do not recommend that the trigger
be adjusted outside of the factory.

REPAIRMAN

PROOF

CLEAN

TEST

TARGET

PATTER

T.A.L.

GALLERY TESTER

DATE

DATE

DATE

DATE

DATE

OFFICE COPY

RD6925 REV. 1/94

PS02343