

File Number:	18734	Arms Service number:	62046
Last Name:	FULLMER	First Name:	COREY
Street:	60 NORTH 100 WEST	City:	CIRCLEVILLE
State:	UT	Zip:	84723
Home Ph:			
Work Ph:		Product Type:	F F A T O
Type Concern:	S	PI PD P S	Concern Code:
			1027
Concern:	FAIL TO FIRE		
Cause Code:	4015	Cause:	IMPROPER MAINTENANCE
Assigned To:	SANITA	Classification:	UNJ UNJ UNC UND J
Settlement Detail:	REPAIR AT SPEC PRICE	Settlement Amount:	\$0.00
Date Opened Rem:	2/21/2003	Date Opened by P/S:	2/21/2003
Caliber:	7MM MAG		
Date of Incident:		Date Closed:	2/21/2003
Bullet Weight:			
Date to Analysis:		Date from Analysis:	
Manufacturer:	REM		
Model:	700	Serial:	B6318844
Date Code:	KB	Date Mfgd:	5/1/1981
RAMAC:	700	Litigation:	☐
PreLitigation:	☐	Obsolete:	☐
Custody:		Comments:	upon receipt sear safety cam seized up inside the trig housing, poor maintenance Repair and Shipping documents 3/21/03.
Time of Modification:	1:51:57 PM		
Date of Modification:	2/21/2003		