

Repair Order Number



Repair Order Number RE00062046	Description/Serial Number B6318844	Repairman - Bruce Travis Date Received - 3/7/2003
Account # - R-	Model 700 Center Fire Caliber: 7 MM MAG BDL	Estimate Date - 2/24/2003 Current Date - 3/19/2003
Customer COREY FULLMER 60 NORTH 100 W CIRCLEVILLE. UT 84723 US		Return To COREY FULLMER 60 NORTH 100 W CIRCLEVILLE. UT 84723 US
Phone (H) (435)-577-2881 Phone (W)	Fax (435)-577-2512 Email coreyf@piute.k12.ut.us	

Problems			
Reported		Found	
M992	FOLLOW DOWNS	M123	FORWARD TO PRODUCT SERVICE F
M993	SAFETY NOT WORKING		

Repair					
Material #	MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part					
F26345	700 TRIG ASSB RH	1	1	0	Y
Part Total:		1	1	0	
Service					
4000119	GR-TEST	1	1	0	Y
4000104	ARMS SERV SHIPPING & HANDLING	0	0	0	N
4000116	GR-LABOR	20	20	0	N
Service Total:		21	21	0	

ProblemNotes	mfg date 5/81 action and trigger assm covered with a heavy sticky substance - parts seized up - poor maintenance replace trigger assm and clean action \$20.00 quote				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date