

File Number: 18762		Arms Service number: 62249	
Last Name: FIELDS		First Name: STAN	
Street: 156 SEITZ DRIVE		City: SALINA	
State: KS	Zip: 67401	Home Ph: 785-827-1186	
Work Ph:	Product Type: F	F A T O	
Type Concern: S	PI PD P S	Concern Code: 1008	
Concern: FIRED ON BOLT CLOSING			
Cause Code: 4015	Cause: IMPROPER MAINTENANCE		
Assigned To: SUPRY	Classification: UND	UNJ UNC UND J	
Settlement Detail: BLM PROGRAM	Settlement Amount:		\$0.00
Date Opened Rem: 3/4/2003	Date Opened by P/S: 3/4/2003	Caliber:	270
Date of Incident:	Date Closed: 3/4/2003	Bullet Weight:	
Date to Analysis:	Date from Analysis:	Manufacturer:	
Model: 700	Serial: 6637675	Date Code: KX	Date Mfgd: 5/25/1973
RAMAC: 700	Litigation: ☐	PreLitigation: ☐	Obsolete: ☐
Custody:	Comments: Sear sticks to sidewalls of housing due to sticky residue build-up. Quote \$20 for cleaning action and installing new TA under the bolt lock modification program. Repair and shipping documents 3/31/03.		
Time of Modification: 11:37:16 AM			
Date of Modification: 3/4/2003			