

Safety back on, reached down
got hold of the bolt to eject the
round again, as soon as I started
to raise the bolt the round discharged.
I then finished opening the bolt,
ejected the spent cartridge, took
the bolt out checked and could
not find any apparent damage to
the bolt, so I replaced the bolt and
tried firing again, it worked
good, I finished lighting the rifle up
used it to hand deer with last fall.
This fall I got it out to make sure
The scope was still lighted up, and
the same problems all over again.
Please check the rifle out to
see what the problem is. I only
use Remington factory load 150gr.
PLSP in it. Remington is the only shell
I use in all my rifles & shotguns.

Thank you
Daryl D. Decker

Remington 700-BDL-270
SN# B6477687

I bought this Rifle Last Spring used, The man That had it before me told me He had bought it for his Son to Deer hunt with but was too Much for Him and He'd only Had Eight (8) Rounds fired Through it. I put a Scope on it last fall, took it out to Light it up, when I put 3 on it and Closed The Bolt, Then Aimed at the Target, pushed the Safety to fire position, pulled the trigger but it acted like the Safety hadn't released because the trigger wouldn't pull back, I then put the Safety back on, ejected the round, Checked it for any damage, when there was none found, I returned the round, closed the bolt, put the Safety to fire, Squeezed the trigger and it still would not pull, I then put the