

Remington.

TRACKING DOCUMENT

Repair Order Number



Repair Order Number RE00087324	Description/Serial Number 7775242	Repairman - Robert Frink Date Received - 11/2/2004
Account # - R-	Model 7 Center Fire Caliber: 7 MM REM SA ULTRA MAG	Estimate Date - Current Date - 11/6/2004
Customer MICHAEL FAIRMAN 3547 ORCHARD HTS RD NW SALEM, OR 97304 US		Return To MICHAEL FAIRMAN 3547 ORCHARD HTS RD NW SALEM, OR 97304 US
Phone (H) (503)-364-6186 Phone (W)		Fax Email

Reported		Found	
M123	FORWARD TO PRODUCT SERVICE FOR INSPECTION	M123	FORWARD TO PRODUCT SERVICE F
M992	FIRE WHEN RELEASING SAFETY		

Material #		MaterialDesc	Quantity Needed	Quantity From Inv	Quantity From Kit	Warranty (Y/N)
Part						
F92458	7	TRIGGER ASSB	1	1	0	Y
Part Total:			1	1	0	
Service						
4000104		ARMS SERV SHIPPING & HANDLING	0	0	0	Y
4000119		GR-TEST	1	1	0	Y
Service Total:			1	1	0	

ProblemNotes	Trigger pull screw adjusted beyond length of return spring not allowing proper return of trigger. Replace complete trigger assembly at no charge under warranty.				
Repairman	Proof	Clean	Test	Target	Pattern
Gallery Tester	Date	Date	Date	Date	Date